Art.version

D1.0452

ZYYXs dok.kod/ZYYX's doc. code

Artikelnamn/Article name ZYYX proABS



ZYYX proABS - MSDS

ACCORDING TO REGULATION (EC) NO. 1907/2006 AND REGULATION (EU) NO 453/2010 (REACH)

1. Identification of the substance/mixture and of the Company

1.1. Product identifier

Trade name: ZYYX proABS

1.2. Relevant identified uses of the substance or mixture and uses advised against

General use: Polymer for 3D printing applications

1.3. Details of the supplier of the safety data sheet

Company name: Magicfirm Europe AB

Address: Holtermansgatan 1 B

Postal Code, city: SE-411 29 GOTHENBURG, SWEDEN

WWW: www.zyyx3dprinter.com

E-mail: info@zyyx3dprinter.com

Telephone: +46 (0)31 799 57 17

2. Hazards identification (Directive 1272/2008/EEC and GHS)

2.1 Classification: Not dangerous according to Directive 1272/2008/EEC.

2.2 Label elements: Not a hazardous substance or mixture.

2.3 Other hazards: Not known.

3. Composition / information on ingredients

3.1. Mixture

Acrylonitrile-co-butadiene-co-styrene Polyethylene terephthalate Polycarbonate

SVHC: None of the substances, named in the Candidate list art. 59 (1,10) of the REACH regulation EC no. 1907/2006 has been used in a concentration >0,1 %.

 ZYYXs dok.kod/ZYYX's doc. code
 Art.version
 Dok.u

 D1.0452
 A

Dok.utgåva/issue – Datum/dateArtiA - 2017-07-10ZY

Artikelnamn/Article name ZYYX proABS Art.kod/Art.code Godkänd/Appr. F2.0402



4. SECTION 4: First aid measures

4.1. Description of first aid measures

General advice: If you feel unwell, seek medical advice (show the label where possible). Never give anything by mouth to an unconscious person. Take off contaminated clothing and shoes immediately. **If inhaled:** If breathed in, move person into fresh air.

In case of skin contact: If on skin, rinse well with water. If skin irritation persists, seek medical attention. **In case of eye contact:** If easy to do, remove contact lens, if worn. In the case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

If swallowed: Rinse mouth with water. Induce vomiting immediately and call a physician. If a person vomits when lying on his back, place him in the recovery position.

4.2. Most important symptoms and effects, both acute and delayed

Treat burns as thermal burns. The material will come off as healing occurs; immediate removal from skin is not necessary.

4.3. Indication of any immediate medical attention and special treatment needed

no data available.

5. Firefighting measures

Material can accumulate static charges which may lead to an electrical spark. Use proper bonding and/or grounding procedures.

5.1. Extinguishing media

Suitable extinguishing media: Foam, water spray jet, dry chemical. Unsuitable extinguishing media: High volume water jet.

5.2. Special hazards arising from the substance or mixture

Specific hazards during firefighting: Do not use a solid water stream as it may scatter and spread fire. Exposure to decomposition products may be a hazard to health.

5.3. Advice for firefighters

Special protective equipment for firefighters: Wear self-contained breathing apparatus for firefighting if necessary. Use personal protective equipment.

Further information: Standard procedure for chemical fires. Use extinguishing measures that are appropriate to local circumstances and the surrounding environment. In the event of fire and/or explosion do not breathe fumes.

 ZYYXs dok.kod/ZYYX's doc. code
 Art.version
 Dok.utgåva/issue – Datum/date

 D1.0452
 A - 2017-07-10

Artikelnamn/Article name ZYYX proABS Art.kod/Art.code Godkänd/Appr. F2.0402



6. SECTION 6: Accidental release measures

6.1 Personal precautions, protective equipment and emergency procedures: Refer to protective measures listed in sections 7 and 8. Avoid dust formation. Avoid breathing dust. Avoid breathing gases released from molten filament. Ensure adequate ventilation, especially in confined areas.

6.2 Environmental precautions: No data available.

6.3 Methods and materials for containment and cleaning up: Allow molten material to solidify. Use mechanical handling equipment. Keep in suitable, closed containers for disposal. Clean contaminated surface thoroughly.

6.4 Reference to other sections: see chapter: 7, 8, 11, 12 and 13.

7. SECTION 7: Handling and storage

7.1. Precautions for safe handling

Advice on safe handling: For personal protection see section 8. Avoid creating dust. Do not breathe dust. Avoid contact with molten material. Avoid contact with skin and eyes.

Advice on protection against fire and explosion: Normal measures for preventive fire protection. **Dust explosion class:** No data available.

7.2. Conditions for safe storage, including any incompatibilities

Requirements for storage areas and containers: Keep containers tightly closed in a dry, cool and ventilated place.

Further information on storage conditions: Protect from moisture.

Advice on common storage: Keep away from oxidising agents and strongly acid or alkaline materials. Keep away from food, drink and animal feedingstuffs.

7.3. Specific end use(s)

Filament for 3D printing.

8. SECTION 8: Exposure controls/personal protection

8.1. Control parameters

DNEL: Dnel/Dmel-values are not available. **PNEC:** PNEC-values are not available.

8.2. Exposure controls

Eye protection:	Use safety goggles for continuous stare at printing.
Skin and body protection:	Good practices suggest to minimize skin contact. When material is heated,
	wear gloves and possibly apron to protect against thermal burns.
Respiratory protection:	In the case of dust or aerosol formation use respirator with an approved filter.
	Half mask with a particle filter P2 (EN 143).

ZYYXs dok.kod /ZYYX's doc. code D1.0452	Art.version —	Dok.utgåva/issue – Datum/date A - 2017-07-10	Artikelnamn/Article name ZYYX proABS	Art.kod/Art.code F2.0402	Godkänd/Appr.	3D Printer
Hand protection Hygiene measure Engineering mea	es:	General indust skin, eyes and before breaks Wash contami	rdance with good in rial hygiene practice clothing. When usin and at the end of we nated clothing befor ate ventilation.	e. Do not breat ng do not eat, d orkday.	he dust. Avoi	d contact with

9. Physical and chemical properties

9.1. Information on basic physical and chemical properties

Appearance:	filament wire
Colour:	various
Odour:	Neutral.
Odour Threshold:	no data available.
Flash point:	no data available.
Ignition temperature:	not applicable.
Thermal decomposition:	≥280 °C.
Lower explosion limit:	not applicable.
Upper explosion limit:	not applicable.
Explosive properties:	no data available.
Flammability:	no data available.
Oxidizing properties:	no data available.
Auto-ignition temperature:	no data available.
Burning number:	no data available.
Molecular Weight:	no data available.
pH:	no data available.
Melting point/range:	225 - 245 °C.
Vapour pressure:	no data available.
Density:	1.1 g/cm ³ .
Bulk density:	no data available.
Water solubility:	insoluble.
Solubility in other solvents:	acetone.
Viscosity, dynamic:	no data available.
Viscosity, kinematic:	no data available.
Evaporation rate:	no data available.

9.2. Other information

None known.

10. Stability

10.1 Reactivity: no data available.**10.2 Chemical stability:** The product is chemically stable.

👝 7////

ZYYXs dok.kod/ZYYX's doc. code	Art.version	Dok.utgåva/issue – Datur
D1.0452	-	A - 2017-07-10

Artikelnamn/Article name ZYYX proABS



10.3 Possibility of hazardous reactions: No decomposition if stored and applied as directed.

10.4 Conditions to avoid: Print temperatures above 260 °C (at standard printing speeds)

10.5 Incompatible materials: Materials to avoid: Strong oxidizing materials.

e – **Datum**/date

10.6 Hazardous decomposition products: Build-up of dangerous/toxic fumes possible in cases of fire/high temperature.

11. Toxicological information

11.1. Information on toxicological effects

Principle routes of exposure:	Eye contact, skin contact, inhalation, ingestion
Acute toxicity:	Not applicable.
Skin corrosion/irritation:	Not irritating.
Serious eye damage/eye irritation:	No data available.
Respiratory or skin sensitization:	No sensitization.
Reproductive toxicity:	No data available.
Carcinogenicity:	No data available.

12. Ecological information

12.1 Toxicity:	Not applicable, no relevant information available.
12.2 Persistence and degradability:	Difficult to degrade.
12.3 Bioaccumulative potential:	No data available.
12.4 Mobility in soil:	No data available.
12.5 Results of PBT and vPvB assessment:	No data available.
12.6 Other adverse effects:	No data available.

13. Disposal considerations

13.1. Waste treatment methods

Advice on disposal and packaging: Disposal: In accordance with local and national regulations. Do not dispose of together with household waste. Waste codes should be assigned by the user based on the application for which the product was used.

14. Transport information

ADR:	Not dangerous goods.
RID:	Not dangerous goods.
IATA:	Not dangerous goods.
IMDG:	Not dangerous goods.
Special precautions for user:	Not applicable.

ZYYXs dok.kod/ZYYX's doc. code	Art.version	Dok.utgåva/issue – Datum/date
D1.0452	-	A - 2017-07-10



15. Regulatory information

15.1. Safety, health and environmental regulations/legislation specific for the substance or mixture

Directive 96/82/EC:	Update 2003.
	Directive 96/82/EC does not apply.
Further information:	Reserved for industrial and professional use.

15.2. Chemical Safety Assessment

no data available.

16. Other information

Full text of H-Statements referred to under sections 2 and 3.

The information provided in this MSDS is based on current knowledge and experience. This information is provided without warranty. This information should help to make an independent determination of the methods to ensure proper and safe use and disposal of the filament.

Document history

Issue	Date	Done by	Change	
А	2017-07-10	ТВ	rst issue of document, based on data from material supplier.	